



Pressed for 2 seconds:

MEM	change distance unit
REF	switch to permanent front reference
CLR	power off
MEM+SMART	angle unit degrees/grad
MEM+FUNC	silent mode on/off
REF+MINUS	beep on/off
REF+PLUS	display illumination on/off
REF+FUNC	back reference case/endpiece
CLR+SMART	calibration mode on/off
CLR+MEM	clear unsent memory
CLR+FUNC	Bluetooth on/off
CLR+MINUS	locked power on/off

FUNC:

1. Shows the actual battery voltage and the battery chemistry
2. Versions
3. Display illumination, edit: 2 sec. PLUS+MINUS, use +/-
4. Endpiece offset, edit: 2 sec. PLUS+MINUS, use +/-

